1881888
Victorian Plant Stand

Parts and Hardware List

A.	Top	1 pc
B.	Spindles	4 pcs
C.	Bottom Shelf	1 pc
D.	Legs	4 pcs
E.	Allen Head Wrench	1 pc
F.	Short Allen Head Bolts	12 pcs
G.	Lock Washers	16 pcs
H.	Flat Washers	16 pcs
I.	Long Allen Head Bolts	4 pcs

∗ Please make sure that you have all the parts and hardware indicated above before you begin assembly of this item.
∗ Use the hardware illustrations to determine correct piece and size.
∗ This item should be assembled on a soft surface to prevent scratching the finish during assembly.
∗ This item may require periodic tightening.

Hardware Illustrations



F. Short Allen Head Bolt



I. Long Allen Head Bolt

G. Lock Washer



H. Flat Washer

1881888
Victorian Plant Stand

Attach the Spindles

Parts required

A.	Top	1 pc	F.	Short Allen Head Bolts	8 pcs
B.	Spindles	4 pcs	G.	Lock Washers	8 pcs
E.	Allen Head Wrench	1 pc	H.	Flat Washers	8 pcs

1. Place the Top (A) up side down on the floor.
2. **Attach Spindles (B)** Align the pre-drilled holes in the Spindles (B) with the pre-threaded holes in the Top (A). Secure in place with the Short Allen Head Bolts (F), Lock Washers (G) and Flat Washers (H) using the Allen Head Wrench (E). See Illustration #1



Illustration # 1

1881888
Victorian Plant Stand

Assemble the Base

Parts required

C.	Bottom Shelf	1 pc	F.	Short Allen Head Bolts	4 pcs
D.	Legs	4 pcs	G.	Lock Washers	4 pcs
E.	Allen Head Wrench	1 pc	H.	Flat Washers	4 pcs

3. **Attach Legs (D)** Align the pre-threaded holes in the Legs (D) with the pre-drilled holes in the pre-cut grooves in the Bottom Shelf (C). Secure in place with the Short Allen Head Bolts (F), Lock Washers (G) and Flat Washers (H) using the Allen Head Wrench (E). See Illustration #2



Illustration # 2

1881888
Victorian Plant Stand

Attach the Base

Parts required

E.	Allen Head Wrench	1 pc	H.	Flat Washers	4 pcs
G.	Lock Washers	4 pcs	I.	Long Allen Head Bolts	4 pcs

4. **Attach Base** Align the pre-drilled holes in the Bottom Shelf (C) with the pre-threaded holes in Spindles (B). Secure in place with the Long Allen Head Bolts (I), Lock Washers (G) and Flat Washers (H) using the Allen Head Wrench (E). See Illustration #3



Illustration # 3